KEKO

NEW JERSEY STATE DEPARTMENT OF ENVIRONMENTAL PROTECTION

TO	Spill File	HAY 11 2 16 PH DATE May 4, 1951				
FRON'	Lawrence Muzyka	May !!	2 16 1	DATE <u>May</u>	4, 1991 .	
SUBJECT	DEP Inspection at TIFA Limited,	. hon Rail	HS&E	,i. ò 		_

Thursday, March 26, 1981

1403- At the request of Bruce Schwartz, I conducted an inspection of the TIFA facility in Millington, NJ. I was accompanied by Grog Curningham, Division of Water Resources, and Lisa Fleming, Bureau of Pesticides. We were escorted by Mr. Armold Livingston, TIFA manager, and Mr. Joseph S. Seidel, the counselor for TIFE.

Before proceeding to inspect the facility, we met in the conference room to discuss the purpose of the inspection. Mr. Livingston stated in the conference room that no pesticides are handled at this facility. We examined photographs of the various equipment manufactured and assembled at this plant.

We proceeded to inspect the building. A list of all the tenants was provided and the locations of these tenants was designated on a drawing as we walked mast these facilities (See list of temants).

A full inspection of the facility was conducted. I observed and was informed by Mr. Livingston that for machines, sprayers, and trailers are manufactured and assembled at the facility. My observation indicated that no apparent use or manulacture of pesticides or other hazardous materials was observed at the time of the inspection. A large amount of space is not presently utilized at the facility.

Er. Livingston introduced us to a few employees, demonstrating that most of the employee's were foreigners. I observed a stack of recently painted 55 gallon drums at the site. I impaired as to why the paint was still wet and why the drums were tainted in the building. Mr. Livingston stated that the drums were used to store fuel oil for equipment testing. They were painted for resale. I inquired about drainage lined in the building. I was assured that no storm drains are accessible in the building, but only sanitary sever lines. A bathroom and sanitary sever connection was observed in the area of the empty drums.

In a large room in the building, I observed a large puddle of water, a spray machin and a 55-gallon drum filled with kerosene. Mr. Livingston identified the drums as containing kerosene. The water was attributed to a broken water pipe. Mr. Livings stated that the sprayer was being tested. He could not elaborate stating that the new device was proprietary.

We proceeded to the outside of the facility and we discussed the history of the . asbestos pile. Apparently, the Solid Waste Administration had been actively incolved in the asbestos state of affairs in the past. Mr. Seidel stated that correspondence exists between SWA and TIFA.

ASB 002 015

ty observation of the ashestos yile outlid not deture the if may ashestos and uniterimy the uniters of the State. They County has all his read on a time best time to rake a determination would be suring a consider of the Sundhyber syreed to consider say ling in the future.

Jar. olucion

No usage, handling or manufacture of posticides was observed during the unspection at the TIFA facility. It appears that the operation consists assembly of spray equipment. No conclusion can be drawn at this time about the discharge of aspestos into the waters of the State from the observations. Additional sampling may be warranted and it should be conducted during a rain event.

Laurence Muzyka

11::30

co: Dave Reger Bruce Schwartz Greg Curris dur